

Flywheel Locking Pins

BMW 2.0 | 3.0 Diesel Engines



Description

These 2 Flywheel Locking Pins are required to extend the coverage of the Eldon Part No 23048-20.

The exact pin required is not always identified by Autodata and other technical sources therefore both pins are required to give the full choice.

Which pin is required is dependent on transmission type and there are many different types of transmission.

Packaging

Bartender Box

Additional Information

23 November 2011